

METAL NAIL PLUG SPIX

Mounting






1. Place the detail in position.
Drill through the studs straight into the underlying concrete.
Drill dimension according to the tabel below.



2. Push in the Spix, so-called drill-through installation.



3. Knock in the nail so the sleeve expands into the concrete.

Load capacity

Dimension Ø x L	Concrete C28/35 Tension load	Concrete C28/35 Shear load	
mm 5x22	kN/kg 0,5/50	kN/kg 0,3/30	
6x40	0,98/98	0,5/50	

Technical info

Dimension Ø x L	Max. Fixture thickness	Min. mounting depth	Drill bit Ø
mm	mm	mm	mm
5x22	6	16	5
6x40	20	20	6